



Where possible mount the sensor as high as possible on a north facing vertical surface.

Ensure that all cable entry to the enclosure is via suitable cable glands and seal with silicone sealant.

If it is necessary to screw through the rear of the enclosure ensure that any holes are covered with the caps provided and sealed with silicone sealant where appropriate.



Rear view of Sensor

